


General Service | £50


- Safety inspection for loose or worn parts
- Front and rear wheels trued
- Hubs, headset and bottom bracket adjusted as needed
- Tighten and adjust braking and shifting components
- Lubricate all pivot points



General Service + Drivetrain | £65

General Service plus...

- Bicycle degreased, washed and polished
- Front and rear hubs adjusted off the bike



Full Service | £120

General Service + Drivetrain plus...

- All parts removed so frame/fork can be cleaned and detailed
- Remove, clean, inspect and grease brake and shift cables
- Remove, clean, inspect and adjust:
 1. Front and rear hubs
 2. Headset
 3. Bottom bracket
 4. Derailleur pulleys
- Replace grips or handlebar tape (parts extra)

